



Preventative Maintenance

After proper installation of your *QuickSilver*[®] or *DURAPRO*[™] liner, attention to the following areas of preventative maintenance will help maintain the performance and extend the life of you liner.

> **LINER TRAPPED UNDER LEADING EDGE PROTECTOR**

If the liner is not allowed to expand freely, buckling will occur. Periodically check for and remove bends, dents or kinks in the leading edge protector. It's also important to remove bulk materials that may have become lodged between the edge protector and liner. These conditions could "trap" the liner, preventing movement needed for thermal expansion.

> **MATERIAL TRAPPED UNDER LINER**

Material under the liner will cause accelerated wear and can cause holes in the liner. Fines can accumulate during unloading or tailgate closing. Check daily for fines under the liner and remove them.

> **ASPHALT EMULSION BUILD-UP ON LINER**

Bulk materials can stick to emulsion build-up. Emulsion used as an asphalt binder can accumulate on the liner. Use a chemical release agent (check local regulators for proper usage), or rotate asphalt with abrasive loads to wear away the build-up.

> **LINER BUCKLING**

Incorrect loading patterns of hot products can cause buckling and liner failure. Dropping the first load in the center can cause buckling of the liner towards the front. To reduce the risk, place the first dump in the very front of the body (on the doghouse). Subsequent loads should be front to back.

> **HOT ASPHALT**

QuickSilver[®] liners in 1/2" gauge have been field tested to withstand the heat of asphalt up to 350°F. Hauling asphalt heated to more than 350°F will cause the liner to pit, and material will become embedded in the liner. Hauling those loads constitute improper use of the liner. *DURAPRO*[™] liners are not designed to handle hot asphalt. Doing so will cause performance problems and invalidate the warranty.

LINER FAILURES CAUSED FROM IMPROPER USE, MAINTENANCE OR INSTALLATION ARE NOT COVERED UNDER THE WARRANTY.

If you have any question about the performance of your *QuickSilver*[®]/*DURAPRO*[™] liner, please contact your authorized dealer.



ROQUADRANT

INDIANAPOLIS, IN

4243 West Bradbury Avenue
Indianapolis, IN 46241
800-535-9545
317-244-1311

OMAHA, NE

10308 South 144th Street
Omaha, NE 68137
800-535-8552
FAX: 402-895-6129

STREETSBORO, OH

8540 State Route 14
Streetsboro, OH 44241
888-237-2262
FAX: 330-626-3277

AERO-KIT

BURLINGTON, ON
3474 Mainway Drive
Burlington, OH L7M 1A8
800-465-8277
FAX: 905-335-8499

**AERO UK LTD • UNITS 1 & 2
BUCCANEER COURT**

Airfield Business Park
Elvington, York - North Yorkshire, YO41 4AU
01904-607411
FAX: 01904-607412

